

TECHNICAL DATASHEET WS ESD SCARF



D és Tsa Bt. • 2600 Vác, Galcsek u. 8-10. • Tel.: +36 27 502 555 • Fax: +36 27 200 835 • sales@destsa.hu • destsa.hu • dlb.hu



- » Standard sizes: Unisex, one size
- With ESD logo
- » Comfortable
- Warm and breathable



- » Static dissipative knitted fabric (with carbon yarn)
- » Finish: Crease resists, workwear
- » Charging time: < 2 seconds</p>
- » Complies with IEC 61340-4-9:2024 and ANSI/ESD STM2.1:2018, and keeps this compliance after more than 40 industrial washings
- » Developed for industrial washing

PS21

- » Composition: 50% Cotton 47% Polyester 3% Conductive fibre
- » Fabric weight: 210 g/m²
- » Resistance from point to point (Rp): 10⁶ 10⁷ Ohm

EECO-PS2

- » Composition: 48% Cotton 48% Polyester 4% Conductive fibre
- Fabric weight: 215 g/m²
- » Resistance from point to point (Rp): < 10° Ohm</p>

FL1

- » Composition: 96% Polyester 4% Conductive fiber
- » Fabric Weight: 250 g/m²
- » Resistance from point to point (Rp): 109 1011 Ohm











FL1 FABRIC







Clothing certified according to the international ESD o standards, as indicated by this/similar label







WS - PS21 - NB style fabric color



WS ESD SCARF



D és Tsa Bt. • 2600 Vác, Galcsek u. 8-10. • Tel.: +36 27 502 555 • Fax: +36 27 200 835 • sales@destsa.hu • destsa.hu • dlb.hu



You can contact us too for customized embroidered or screen printed company logos, lettering, custom designed ESD clothing.

WASHING INSTRUCTIONS

Conductive carbon fibres used in ESD fabrics are very sensitive to high temperatures, alkalis, acids, rinses (softeners) and bleaches. Inadequate use may cause damage to carbon fibres and ESD clothing may lose or significantly deteriorate ESD parameters. Therefore, wash ESD clothing very carefully, in each case please follow the instructions:

PS21, EECO-PS21 FABRICS

- In the case of knitted fabrics (TS15, TS16, PS21, LY20, THSS,THSB) we suggest to determine personal size with measurement on washed clothes. The sizes given by us in size charts meant values before washing regarding products made from these fabrics.
- We recommend, in order to preserve the conductivity of the garment in the long term, to entrust washing and drying processes to an industrial laundry where they can provide the necessary technological processes and conditions (documented washing procedures and suitable environ-ment). Adapt the associated cleaning processes to the production technology (e.g. cleanroom requirements) of the product at the place of use.
- If the used production technology does not require specific cleaning processes, do washing in cold or lukewarm water at a temperature not warmer than 40 °C (104 °F) with neutral (liquid) detergent.
- Ironing of the garment is not necessary or recommended. If the user does iron the garment, iron at a maximum temperature of 110 °C (230 °F) without steaming.
- **1** Bleachers are forbidden. Do not use rinse aids or detergents with a high alkali or acid content. Do not use detergents and / or rinse aids that contain bleach and / or chlorine.
- 1 Do not use perfumes and deodorants as they may damage the fabric and the color of the product
- 1 Do not dry clean. Tumble drying is prohibited.
- 1 Wash all garments inside out
- 1 Do not expose clothing to direct UV rays. Tighten the zippers before each wash













WS ESD SCARF



D és Tsa Bt. • 2600 Vác, Galcsek u. 8-10. • Tel.: +36 27 502 555 • Fax: +36 27 200 835 • sales@destsa.hu • destsa.hu • dlb.hu



FL1 FABRIC

- 🚺 In order to preserve the long life of ESD clothings, please use industrial laundries who can provide controlled, documented washing procedures and environment
- Wash in cold or not warmer than 40 °C (104 °F) lukewarm water with neutral liquid detergent
- ① Do not use detergents and / or rinse aids that contain bleach and / or chlorine
- Bleachers are forbidden
- ① Do not use rinse aids or detergents with a high alkali or high acid content
- Do not dry clean
- ① Dry in the open air. Tumble drying is prohibited. After centrifugation, hang dry only
- Does not require ironing, but if absolutely necessary, iron at a maximum temperature of 110 °C (230 °F) without steaming
- Wash all items inside out
- Using deodorant can damage the color of the product
- When drying clothes outdoors, do not expose them to direct sunlight
- 1 Tighten the zippers before each wash













WARRANTY

- 1 The warranty is strictly valid under controlled and documented industrial laundry conditions, concern the fabric washing cycle as specified in the technical data's.
- The warranty is NOT valid if the washing process is made in home environment!
- 1 The warranty covers ESD parameters and possible sewing errors according to IEC 61340-4-9:2024 and ANSI/ESD STM2.1:2018 standard issued only!
- The warranty does not cover the size and shrinkage differences within the tolerances given at the size charts!
- ① Our clothing products are provided with the "Operating instructions with symbols" according to the EN ISO 3758:2023 standard.
- If the product shows improper tampering (e.g. tread extension or tearing), the complaint can be rejected.



The availability of products manufactured from the colors shown may vary. For current expected delivery times and other requested colors please contact us.